

VEHICLE INFORMATION

Box 2 - Weight Rating of Truck Power Unit

- The weight rating for most four-tire and some six-tire vehicles is located on a metal plate, on the driver's door edge or door-latch post.
- For larger trucks, the weight rating is usually found on the driver's side of the vehicle, by opening the door and looking at the hinge pillar, door-latch post or door edge.
- On older vehicles, it may be in other locations, such as under the hood or in the glove box. If the vehicle is a bus, enter a dash (-).

Note: The weight rating is not necessarily the weight shown on the registration.

Enter one of the following numbers:

- 1 - Less than or equal to 10,000 lbs.
- 2 - 10,001 - 26,000 lbs.
- 3 - More than 26,000 lbs.

Vehicle Identification Number (VIN)

Enter the VIN from the vehicle registration.

Note: Compare the VIN on the registration with the number on the vehicle. The VIN can be located on the driver's side of the vehicle, in the front corner of the dashboard; on the hinge pillar; door latch post; door edge; or on an interior wall near the driver's seat.

Box 3 - Vehicle Configuration - enter one of the following numbers:

- | | |
|---|--|
| 1 - Bus (seats for more than 15 people, including driver) | 9 - Unknown Heavy Truck, cannot classify |
| 2 - Single-unit Truck (2-axle, 6-tire) | 10 - Passenger Car - only record when vehicle display a Haz Mat placard |
| 3 - Single-unit Truck (3 or more axles) | 11 - Light truck (van, mini-van, panel, pickup, sport utility vehicle) only record when vehicle displays an HM placard |
| 4 - Truck/Trailer | 12 - Bus (seats for 9 - 15 people, including driver) |
| 5 - Truck Tractor (bobtail) | |
| 6 - Tractor/Semi-trailer | |
| 7 - Tractor/Doubles | |
| 8 - Tractor/Triples | |

**TRUCK and BUS SUPPLEMENTAL
POLICE ACCIDENT REPORT**

Local Codes
6074339999
SPIC10060037



MV-104S (10/05)

Mail To: NYS Dept. of Motor Vehicles, Accident Records Bureau,
PO Box 2084, Albany NY 12220-0084

AMENDED REPORT

INSTRUCTIONS You must complete this form:

- if at least one of the vehicles involved is:
 - a truck having a GVWR or GCWR > 10,000 lbs.; or
 - a vehicle with a Haz Mat placard; or
 - a bus designed to carry 9 or more persons, including the driver;
- AND at least one of the following conditions is met:
 - at least one person sustained fatal injuries
 - at least one person was transported for IMMEDIATE medical treatment
 - at least one vehicle is disabled and was towed/transported from the scene.

Number of:
 Trucks having a GVWR or GCWR > 10,000 lbs.
 Vehicles with a Haz Mat placard
 Buses designed to carry 9 or more persons

Number of Vehicles:
 Towed/transported from scene due to damage

Number of Persons:
 Sustaining fatal injuries
 Transported for IMMEDIATE medical treatment.

ACCIDENT DATE: Mo. 05, Day 25, Year 06
 MILITARY TIME: 2230
 COUNTY: OTSE
 CITY/TOWN/VILLAGE: ONEONTA

DRIVER
 LICENSE ID #: 97186543112
 DRIVER NAME: HAIGHT, W, RUSTY
 STATE OF LIC.: CA

LICENSE CLASS
 1 A, 2 B, 3 CDL C, 4 D, 5 DJ, 6 E, 7 M, 8 MJ, 9 OTHER, 10 DM
 DATE OF BIRTH: Mo. 06, Day 17, Year 50
 SEX: 1 Male, 2 Female

CARRIER NAME: CSI FUEL, INC.
 STREET OR P.O. BOX: P.O. BOX 208
 CITY: PLANO, STATE: TX, ZIP CODE: 75075
 TOTAL AXLES (Includes trailers): 5

PLATE NUMBER: 54032
 STATE OF REG.: TX
 CARRIER'S IDENTIFICATION NUMBERS: US DOT 78631241, ICC MC

WEIGHT RATING OF TRUCK POWER UNIT
 1 Less than or equal to 10,000 lbs.
 2 10,001 - 26,000 lbs.
 3 More than 26,000 lbs.

VEHICLE IDENTIFICATION NUMBER: 1XKADR X5MS5620661

VEHICLE CONFIGURATION
 1 Bus (seats for more than 15 people, including driver)
 2 Single-unit Truck (2-axle, 6-tire)
 3 Single-unit Truck (3 or more axles)
 4 Truck/Trailer
 5 Truck Tractor (bobtail)
 6 Tractor/Semi-trailer
 7 Tractor/Doubles
 8 Tractor/Triples
 9 Unknown Heavy Truck, cannot classify
 10 Passenger Car - only record when vehicle displays a Hazardous Material placard
 11 Light truck (van, mini-van, panel, pickup, sport utility vehicle) only record when vehicle displays an HM placard
 12 Bus (seats for 9 - 15 people, including driver)

TRAFFIC WAY
 1 Two-way, not divided
 2 Two-way, divided, unprotected median
 3 Two-way, divided, positive median barrier
 4 One-way not divided
 5 Not reported

CARGO BODY TYPE
 1 Bus (seats for more than 15 people, including driver)
 2 Van/Enclosed Box
 3 Cargo Tank
 4 Flatbed
 5 Dump
 6 Concrete Mixer
 7 Auto Transporter
 8 Garbage/Refuse
 9 Other
 10 Grain, Chips, Gravel
 11 Pole
 12 Bus (seats for 9-15 people, including driver)

ACCESS CONTROL
 1 No Access Control
 2 Full Access Control
 4 Partial Access Control

HAZARDOUS MATERIALS INVOLVEMENT
 Does vehicle have Haz Mat placard? 1 Yes 2 No
 COPY FROM PLACARD:
 4-digit identification number from diamond/orange panel: _____
 1 or 2-digit number from bottom of diamond: _____
 NAME OF HAZ MAT CLASS: _____

SEQUENCE OF EVENTS (FOR THIS VEHICLE)
 1 Ran Off Road (noncollision)
 2 Jackknife (noncollision)
 3 Overturn/Rollover (noncollision)
 4 Downhill Runaway (noncollision)
 5 Cargo Loss or Shift (noncollision)
 6 Explosion or Fire (noncollision)
 7 Separation of Units (noncollision)
 8 Involving Pedestrian (collision)
 9 Involving Motor Vehicle in Transport (collision)
 10 Involving Parked Motor Vehicle (collision)
 11 Involving Train (collision)
 12 Involving Pedalcycle (collision)
 13 Involving Animal (collision)
 14 Involving Fixed Object (collision)
 18 Cross Median/Centerline (noncollision)
 19 Equipment Failure (noncollision) (brake failure, blown tires, etc.)
 20 Other (noncollision)
 21 Unknown (noncollision)
 22 With Work Zone Maintenance Equipment (collision)
 23 With Other Movable Object (collision)
 24 With Unknown Movable Object (collision)

WAS HAZARDOUS CARGO RELEASED FROM VEHICLE (other than fuel from fuel tank)?
 1 Yes 2 No

OFFICER'S RANK AND SIGNATURE: _____
 PRINT NAME IN FULL: _____
 BADGE/ID NO.: _____
 NCIC NO.: _____
 DATE OF REPORT: _____



Box 4 - Cargo Body Type - enter one of the following numbers:

- | | |
|--|---|
| 1 - Bus (seats for more than 15 people,
including driver) | 7 - Auto Transporter |
| 2 - Van/Enclosed Box | 8 - Garbage/Refuse |
| 3 - Cargo Tank | 9 - Other |
| 4 - Flatbed | 10 - Grain, Chips, Gravel |
| 5 - Dump | 11 - Pole |
| | 12 - Bus (seats for 9 - 15 people,
including driver) |

Box 5 - Hazardous Material Involvement

Does vehicle have Haz Mat placard? Enter one of the following numbers:

- 1 - Yes
- 2 - No

Copy From Placard - for buses or trucks, enter the number from the HazMat placard on the vehicle. If the involved vehicle is not placarded, but is carrying HazMat material in a container within the vehicle, enter the placard number that is displayed on the container.

Note: When more than one placard is display on the vehicle, enter the information from only one of the placards.

- 4-digit identification number from diamond/orange panel
- 1 or 2-digit number from bottom of diamond
- Name of HazMat Class - enter the most severe code or name of the "released" material.

Box 6 - Was Hazardous Cargo Released From Vehicle (other that fuel from fuel tank)?

Enter one of the following numbers if any placarded material was released from the cargo tank or compartment of the truck. Do not count fuel spilled from the vehicle's fuel tank, even though it is a hazardous material.

- 1 - Yes
- 2 - No

Box 7 - Sex (see Driver Information above)

Box 8 - Total Axles (see Appendix C)

Local Codes
 6074339999
 SPIC10060037



**TRUCK and BUS SUPPLEMENTAL
 POLICE ACCIDENT REPORT**

MV-104S (10/05)
 Mail To: NYS Dept. of Motor Vehicles, Accident Records Bureau,
 PO Box 2084, Albany NY 12220-0084

AMENDED REPORT

INSTRUCTIONS You must complete this form:

- if at least one of the vehicles involved is:
 - a truck having a GVWR or GCWR > 10,000 lbs.; or
 - a vehicle with a Haz Mat placard; or
 - a bus designed to carry 9 or more persons, including the driver;
- AND at least one of the following conditions is met:
 - at least one person sustained fatal injuries
 - at least one person was transported for IMMEDIATE medical treatment
 - at least one vehicle is disabled and was towed/transported from the scene.

Number of:
 1 Trucks having a GVWR or GCWR > 10,000 lbs.
 1 Vehicles with a Haz Mat placard
 0 Buses designed to carry 9 or more persons

Number of Vehicles:
 1 Towed/transported from scene due to damage
Number of Persons:
 1 Sustaining fatal injuries
 0 Transported for IMMEDIATE medical treatment

ACCIDENT DATE: Mo. 05 Day 25 Year 06 MILITARY TIME 2230 COUNTY OTSE CITY/TOWN/VILLAGE ONEONTA

DRIVER
 LICENSE ID # 9786543112 STATE OF LIC. CA
 DRIVER NAME - exactly as printed on license (Last, First, M.I.)
 HAIGHT, W, RUSTY

1 LICENSE CLASS: 1 A, 2 B, 3 CDL C, 4 D, 5 DJ, 6 E, 7 M, 8 MJ, 9 OTHER, 10 DM. DATE OF BIRTH: Mo. 06 Day 17 Year 50. SEX: 1 Male, 2 Female. **7**

CARRIER
 CARRIER NAME CSI FUEL, INC.
 STREET OR P.O. BOX P.O. BOX 208 CITY PLANO STATE TX ZIP CODE 75075 TOTAL AXLES (Includes trailers) 5

PLATE NUMBER 54032 STATE OF REG. TX CARRIER'S IDENTIFICATION NUMBERS: US DOT 78631124 ICC MC

3 WEIGHT RATING OF TRUCK POWER UNIT: 1 Less than or equal to 10,000 lbs., 2 10,001 - 26,000 lbs., 3 More than 26,000 lbs. VEHICLE IDENTIFICATION NUMBER: 1XKADR5MS5620661

6 VEHICLE CONFIGURATION: 1 Bus (seats for more than 15 people, including driver), 2 Single-unit Truck (2-axle, 6-tire), 3 Single-unit Truck (3 or more axles), 4 Truck/Trailer, 5 Truck Tractor (bobtail), 6 Tractor/Semi-trailer, 7 Tractor/Doubles, 8 Tractor/Triples, 9 Unknown Heavy Truck, cannot classify, 10 Passenger Car - only record when vehicle displays a Hazardous Material placard, 11 Light truck (van, mini-van, panel, pickup, sport utility vehicle) only record when vehicle displays an HM placard, 12 Bus (seats for 9 - 15 people, including driver). TRAFFIC WAY: 1 Two-way, not divided, 2 Two-way, divided, unprotected median, 3 Two-way, divided, positive median barrier, 4 One-way not divided, 5 Not reported. **8**

3 CARGO BODY TYPE: 1 Bus (seats for more than 15 people, including driver), 2 Van/Enclosed Box, 3 Cargo Tank, 4 Flatbed, 5 Dump, 6 Concrete Mixer, 7 Auto Transporter, 8 Garbage/Refuse, 9 Other, 10 Grain, Chips, Gravel, 11 Pole, 12 Bus (seats for 9-15 people, including driver). ACCESS CONTROL: 1 No Access Control, 2 Full Access Control, 4 Partial Access Control. **10**

1 HAZARDOUS MATERIALS INVOLVEMENT: Does vehicle have Haz Mat placard? 1 Yes 2 No. COPY FROM PLACARD: 4-digit identification number from diamond/orange panel 112013, 1 or 2-digit number from bottom of diamond: 3. NAME OF HAZ MAT CLASS: FLAMMABLE LIQUID. SEQUENCE OF EVENTS (FOR THIS VEHICLE): 1 Ran Off Road (noncollision), 2 Jackknife (noncollision), 3 Overtum/Rollover (noncollision), 4 Downhill Runaway (noncollision), 5 Cargo Loss or Shift (noncollision), 6 Explosion or Fire (noncollision), 7 Separation of Units (noncollision), 8 Involving Pedestrian (collision), 9 Involving Motor Vehicle in Transport (collision), 10 Involving Parked Motor Vehicle (collision), 11 Involving Train (collision), 12 Involving Pedalcycle (collision), 13 Involving Animal (collision), 14 Involving Fixed Object (collision), 18 Cross Median/Centerline (noncollision), 19 Equipment Failure (noncollision) (brake failure, blown tires, etc.), 20 Other (noncollision), 21 Unknown (noncollision), 22 With Work Zone Maintenance Equipment (collision), 23 With Other Movable Object (collision), 24 With Unknown Movable Object (collision). **11-14**

2 WAS HAZARDOUS CARGO RELEASED FROM VEHICLE (other than fuel from fuel tank)? 1 Yes 2 No. OFFICER'S RANK AND SIGNATURE: PRINT NAME IN FULL. BADGE/ID NO., NCIC NO., DATE OF REPORT.

